Contents

A short biography of Mats Hillert iii

Foreword v

List of contributors vii

Chapter 1

– Introduction to "Nuclear Reaction Radiography" 1

– Original paper 5

Chapter 2

– Introduction to "Paraequilibrium" 7

– Original paper 9

Chapter 3

– Introduction to "Pressure-Induced Diffusion and Deformation During Precipitation, Especially Graphitization" 25

– Original paper 27

Chapter 4

– Introduction to "The Role of Interfacial Energy during Solid State Phase Transformations" 51

– Original paper 53

Chapter 5

– Introduction to "Thermodynamics of Martensitic Transformations" 87

– Original paper 89

Chapter 6

– Introduction to "The Growth of Ferrite, Bainite and Martensite" 111

– Original paper 113

Chapter 7

– Introduction to "A Solid Solution Model for Inhomogeneous Systems" 159

– Original paper 165

Chapter 8

– Introduction to "The Formation of Pearlite" 177

– Original paper 179

Chapter 9

– Introduction to "On the Theory of Normal and Abnormal Grain Growth" 231

– Original paper 233

Chapter 10

– Introduction to "Grey and White Solidification of Cast Iron" 245

– Original paper 247

Chapter 11

– Introduction to "The Role of Interfaces in Phase Transformations" and "Diffusion and Interface Control of Reactions in Alloys" 257

– Original paper 261

Chapter 12

– Introduction to "The Regular Solution Model for Stoichiometric Phases and Ionic Melts" 295

– Original paper 299

Chapter 13

– Introduction to "Diffusion Controlled Growth of Lamellar Eutectics and Eutectoids in Binary and Ternary Systems" 309

– Original paper 311

Chapter 14

– Introduction to "On the Theories of Growth During Discontinuous Precipitation" 321

– Original paper 323

Chapter 15

– Introduction to "The Effect of Alloying Elements on the Rate of Ostwald Ripening of Cementite in Steel" 337

– Original paper 339

Chapter 16

– Introduction to "The Uses of Gibbs Free Energy-Composition Diagrams" 347

– Original paper 351

Chapter 17

– Introduction to "A Treatment of the Solute Drag on Moving Grain Boundaries and Phase Interfaces in Binary Alloys" 401

– Original paper 403

Chapter 18

– Introduction to "Chemically Induced Grain Boundary Migration" 417

– Original paper 419

Chapter 19

– Introduction to "An Analysis of the Effect of Alloying Elements on the Pearlite Reaction" 427

– Original paper 429

Chapter 20

– Introduction to "Thermodynamics of the Massive Transformations" and "Massive Transformations in the Fe-Ni system" 447

– Original paper 449

Chapter 21

– Introduction to "On the Nature of the Bainite Transformation in Steel" 471

– Original paper 473

Chapter 22

– Introduction to "Solute Drag, Solute Trapping and Diffusional Dissipation of Gibbs Energy" 479

– Original paper 481

Credits 507